

# Simon's Test & Tag Services

\*Sample only of free electronic report\*

A.B.N. 96 224 230 957

Certificate No TTT01802

In-service safety inspection and testing of electrical equipment

Ph 0407 800 435

Compliant with Australian Standard AS/NZS 3760:2010

P O Box 2133 East Ivanhoe Vic 3079

LOG BOOK Page 1

Customer Name XYZ Australia (example)

Contact Person Peter Smith

Customer Address 20 Powell St Hawthorn 3124

Phone Number 03-9827-6808

Asset No	Location	Appliance	Make	Model	Description	Test Date	Next Test Due	Pass/Fail	Comments
WS001	Workshop	Planer	Hitachi	F-20A	550711	9/06/2016	FAIL	FAIL	Damaged Lead
WS002	Workshop	Planer	Makita	N1900B	1834547E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS003	Workshop	Planer	Makita	N1900B	5199711E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS004	Workshop	Belt Sander	Makita	G240B	6681785E	9/06/2016	FAIL	FAIL	Damaged Body
WS005	Workshop	Router	Makita	3612	270734	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS006	Workshop	Palm Planer	Ozito	OZPPL280WA	Grey Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS007	Workshop	Scintilga	Bosch	POF500A	Blue Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS008	Workshop	Mixer Drill	Ozito	OZMM1010A	Grey Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS009	Workshop	Router	Hitachi	TR-12	5660293	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS010	Workshop	Planer	Makita	N1900B	2234067E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS011	Workshop	Welder	Microsaf	Microsaf3	Blue Colour	9/06/2016	9/12/2016	Pass	0.1 EBR
WS012	Workshop	Router	Makita	N3701	514676E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS013	Workshop	Orbital Sander	Ryobi	CS33	607768	9/06/2016	FAIL	FAIL	Damaged Gromet & Lead
WS014	Workshop	Battery Charger	Milwaukee	V28C	Red Colour	9/06/2016	9/12/2016	Pass	Insulation Test
WS015	Workshop	Battery Charger	Ryobi	2601050	14.4 V	9/06/2016	9/12/2016	Pass	Insulation Test
WS016	Workshop	Battery Charger	Makita	DC18RA	Blue Colour	9/06/2016	9/12/2016	Pass	Insulation Test
WS017	Workshop	Battery Charger	Dewalt	DE9116 XE	Blue Colour	9/06/2016	9/12/2016	Pass	Insulation Test
WS018	Workshop	RCD Box - 15 Amp	Arlec - 15amp	30ma - 4 Outlet	Red Colour	9/06/2016	9/12/2016	Pass	0.0 EBR (Trip Time 0.030)
WS019	Workshop	Disc Sander	Bosch	PEX270AE	Green Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS020	Workshop	Angle Grinder	Flex	1200 Watt	Red Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS021	Workshop	Iron	General Electric	N/A	Fawn Colour	9/06/2016	9/12/2016	Pass	0.1 EBR
WS022	Workshop	Circular Saw	Makita	5057 KB	Blue Colour	9/06/2016	FAIL	FAIL	Damaged Lead
WS023	Workshop	Welder	CIG	Weldskill 170	Blue Colour	9/06/2016	9/12/2016	Pass	0.1 EBR (New Plug Fitted)
WS024	Workshop	Router	Hitachi	N/A	Green Colour	9/06/2016	FAIL	FAIL	Damaged Lead
WS025	Workshop	Breaker	Hitachi	H65	Green Colour	9/06/2016	9/12/2016	Pass	Insulation Test
WS026	Workshop	Biscuit Joiner	Milwaukee	PJ710	Red Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS027	Workshop	Router	Makita	3612	629045	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS028	Workshop	Router	Makita	3612	108502E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS029	Workshop	A/C Adapter	Plaslude	N/A	Black Colour	9/06/2016	9/12/2016	Pass	Leakage Test
WS030	Workshop	Battery Charger	Bosch	AL3640 CV	Black Colour	9/06/2016	9/12/2016	Pass	Insulation Test (for 36V Drill)

# Simon's Test & Tag Services

\*Sample only of free electronic report\*

A.B.N. 96 224 230 957

In-service safety inspection and testing of electrical equipment  
Compliant with Australian Standard AS/NZS 3760:2010

Certificate No TTT01802

Ph 0407 800 435

P O Box 2133 East Ivanhoe Vic 3079

LOG BOOK Page 2

**Customer Name** XYZ Australia (example)  
**Customer Address** 20 Powell St Hawthorn 3124

**Contact Person** Peter Smith  
**Phone Number** 03-9827-6808

Asset No	Location	Appliance	Make	Model	Description	9/06/2016	9/12/2016	Pass	Comments
WS031	Workshop	Rotary Drill	Ramset	321	Orange Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS032	Workshop	Rotary Drill	Ramset	325	3630632	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS033	Workshop	Rotary Drill	Ramset	321	Orange Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS034	Workshop	Rotary Drill	Ramset	N/A	Orange Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS035	Workshop	Battery Charger	AEG	BL9618	02749J2809	9/06/2016	9/12/2016	Pass	Insulation Test (for cordless Drill)
WS036	Workshop	Circular Saw	Makita	5007MG	0176662	9/06/2016	9/12/2016	Pass	Insulation Test
WS037	Workshop	Circular Saw	AEG	CS725	Blue Colour	9/06/2016	<b>FAIL</b>	<b>FAIL</b>	<b>Damaged Lead</b>
WS038	Workshop	Drill	AEG	800 Watt	Blue Colour	9/06/2016	<b>FAIL</b>	<b>FAIL</b>	<b>Damaged Lead</b>
WS039	Workshop	Drop Saw	Dewalt	DW713	Yellow & Black	9/06/2016	<b>FAIL</b>	<b>FAIL</b>	<b>Does not Power-up</b>
WS040	Workshop	Jet Heater	Jet Fire	J25A	923	9/06/2016	<b>FAIL</b>	<b>FAIL</b>	<b>FAILED Insulation Test</b>
WS041	Workshop	Cut off Saw	Makita	2414B	Blue Colour	9/06/2016	<b>FAIL</b>	<b>FAIL</b>	<b>Safety Switch Broken (has screw)</b>
WS042	Workshop	Angle Grinder	Makita	GA9020	Blue Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS043	Workshop	Circular Saw	Makita	5900B	Blue Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS044	Workshop	Engraver	Vibro Graver	V-74	Fawn Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS045	Workshop	Dremel	Arlec	Plug Pack	Fawn Colour	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS046	Workshop	Extension Lead	HPM (15 Amp)	8m	Orange Colour	9/06/2016	9/12/2016	Pass	0.3 EBR
WS047	Workshop	Extension Lead	Un-Branded	27m	Red Colour	9/06/2016	9/12/2016	Pass	0.3 EBR (2 x new plugs fitted)
WS048	Workshop	Extension Lead	Click	10m	Orange Colour	9/06/2016	9/12/2016	Pass	0.1 EBR
WS049	Workshop	Extension Lead	Un-Branded	10m	White Colour	9/06/2016	9/12/2016	Pass	0.3 EBR
WS050	Workshop	Extension Lead	Click	25m	Red/Yellow Colour	9/06/2016	9/12/2016	Pass	0.3 EBR
WS051	Workshop	Extension Lead	Qinopu	20m	Red Colour	9/06/2016	9/12/2016	Pass	0.2 EBR
WS052	Workshop	Extension Lead	Qinopu	30m	Yellow Colour	9/06/2016	9/12/2016	Pass	0.5 EBR
WS053	Workshop	Extension Lead	Click	25m	Red/Yellow Colour	9/06/2016	9/12/2016	Pass	0.5 EBR
WS054	Workshop	Phone Charger	Nokia	AC5A	Black Colour	9/06/2016	9/12/2016	Pass	Leakage Test
WS055	Workshop	Drop Saw	Makita	LS1211	1036E	9/06/2016	9/12/2016	Pass	Insulation & Leakage Tests
WS056	Workshop	Power Board	HPM	8 Outlet	White Colour	9/06/2016	9/12/2016	Pass	0.0 EBR

**EBR = Earth Bond Resistance (1.0 Ohm is the safety limit per standards AS/NZS 3760:2010)**

**All appliances were visually inspected first for damage and if they passed, were then tested on the PAT Tester to Standards AS/NZS 3760:2010**

\* Re-test frequency may vary and depend on individual companies OH&S requirements \*

Photos of FAILED / Damaged Appliances


\*Sample only of free electronic report\*



\* Tag WS001 FAILED Lead and a Insulation Leakage Test

\* Tag WS002 Had a new plug fitted & passed a re-test

\* Tag WS004 FAILED - Damaged Body



\*Tag WS005 Had a new plug fitted and passed a re-test

\* Tag WS013 FAILED - Damaged Lead & Grommet

\* Tag WS023 Had a new 15Amp plug fitted & past re-testing



\* Tag WS022 FAILED - Damaged lead

\* Tag WS022 FAILED - Damaged lead

\* Tag WS024 FAILED - Damaged Lead (short) & Body

Photos of FAILED / Damaged Appliances

\*Example of tested appliance register\*



\* Tag WS029 Unable to test - A/C charger missing



\* Tag WS037 Saw FAILED - Damaged Lead



\* Tag WS037 Saw FAILED - Damaged Lead



\* Tag WS038 FAILED - Drill with a Damaged Lead



\* Tag WS038 FAILED - Drill with a Damaged Lead



\* Tag WS039 Drop Saw FAILED - Does not Power-up



\* Tag WS040 Jet Heater FAILED an Insulation Test



\* Tag WS041 FAILED a Visual Inspection - Has a screw locking the top safety switch on



\* Re-test frequency may vary and depend on individual companies OH&S requirements \*