



Simon's Test & Tag Services

A.B.N. 96 224 230 957

In-service safety inspection and testing of electrical equipment
Compliant with Australian Standard AS/NZS 3760:2010

Certificate No TTT01802

Ph 0407 800 435

P O Box 2133 East Ivanhoe Vic 3079

LOG BOOK Page 1

Customer Name MP Australia (example)
Customer Address 20 Powell St Box Hill 3127

Contact Person Peter Smith
Phone Number 03-9827-6803

Asset No	Tag Number	Appliance	Make	Model	Description	Test Date	Next Test Due	Pass/Fail	Comments
MP001	060218	Heat Gun	Makita	HG6003	54257 (201208)	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP002	060219	Extension Lead	Un-Branded	21m	Orange & Black	19/02/2016	19/05/2016	Pass	0.4 EBR - new plug fitted
MP003	060220	Battery Charger	Makita	DC18RD	Black Colour	19/02/2016	19/05/2016	Pass	Insulation Test
MP004	060221	A/C Adapter	Paslode	12VDC800	Black Colour	19/02/2016	19/05/2016	Pass	Leakage Test
MP005	060222	Electric Sander	Makita	BO4553	3300539	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP006	060223	Electric Sheers	Makita	JS8000	00008463/K	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP007	060224	Multi Tool	Bosch	PMF 180E	Green Colour	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP008	060225	Rotary Drill	Bosch	GBH 2-260 FR	Blue Colour	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP009	060226	Circular Saw	Makita	5007NB	Blue Colour	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP010	060227	A/C Adapter	Makita	12V / 1A	Black Colour	19/02/2016	19/05/2016	Pass	Leakage Test - for Radio
MP011	060228	Compressor	Arlec Enforcer	24L Tank	Red Colour	19/02/2016	19/05/2016	Pass	0.6 EBR
MP012	060229	Jigsaw	Makita	4341FCT	1453259	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP013	060230	Angle Grinder - 230	Bosch	GWS22-230LV	Blue Colour	19/02/2016	19/05/2016	Pass	Insulation Test
MP014	060231	Trimmer	Makita	Q04381	00293963	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP015	060232	Planer	Makita	KP0800	00033070	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP016	060233	Extension Lead	Click	5m	Yellow Colour	19/02/2016	19/05/2016	Pass	0.2 EBR
MP017	060234	Extension Lead	Un-Branded	25m	Black & Yellow	19/02/2016	19/05/2016	Pass	0.4 EBR
MP018	060235	Electric Drill	Makita	HP1501	Blue Colour	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP019	060236	Drop Saw	Makita	LS0714	00053511	19/02/2016	19/05/2016	Pass	Insulation & Leakage Tests
MP020	060237	RCD Box	Detroit	30ma - 4 Outlet	Orange Colour	19/02/2016	19/03/2016	Pass	0.1 EBR Leakage Tests 20ms trip
MP021	-	RCD Box	Clipsal	30ma - 4 Outlet	Orange Colour	19/02/2016	FAIL	FAIL	DAMAGED LEAD
MP022	060238	Router	Makita	3612	190477	19/02/2016	19/05/2016	Pass	0.5 EBR

EBR = Earth Bond Resistance (1.0 Ohm is the safety limit per standards AS/NZS 3760:2010)

All appliances were visually inspected first and if they passed, were then tested on the PAT Tester to standards AS/NZS 3760:2010

As requested, a total of 22 appliances were tested with a 3 month green tag used on all the appliances that passed except the RCD Box - monthly



* Appliance MP002 Passed a re-test after a new plug was fitted to the damaged lead



* Appliance MP021 FAILED - Damaged Lead